

19 March 1991

To: P. Buck

Re: New Production Test Procedures
ALL ST-8000A Operations

1. Make four copies of each procedure.
2. Punch all copies (not originals) for 3-hole binder
3. Stamp each page of the copies with "APPROVED MARCH 19 1991".
4. Make four sets of 3-ring binder tabs. Labels:

MODEM BD - A1
CONTROL BD - A2
KEYPAD - PT723-08001
FR PANEL - A3C
POWER SUPPLY - A4
CABLES - A5Wx
PCB INST - A6A
FINAL ASBLY - A6B
TEST FIXTURES
ENVIRONMENT TESTS
INSTR CALIBRATION

5. Install four copy sets and tabs in 1.5" Binders.
6. Place attached labels on front and edge of binders.
7. Distribute:

ORIGINALS: Configuration Control (GWH)
COPY #1: Configuration Manager (GWH)
COPY #2: Production Test (MT/TLS)
COPY #3: Quality Assurance (SH)
COPY #4: Engineering (RD)

G. W. Henry
Configuration Manager